

FIG. 2




FIG. 3




FIG. 4(A)

Return product lacking assembly file code : PL01032902

PL01032902

List : Return product ID/Client code/Product category code

1.0000001356/1J0ADSX80002/PC7101FAA128

Item	Assembly code	Quantity	Content
1	113823-121	1	PRODUCTBRICK
2	159224-001	1	ACADPT
3	178655-002	1	CARD,NIC-1
4	180680-121	1	QRCDKIT
5	182761-051	1	3RDPARTY
6	191841-002	1	CARD,RTFLOCATI
7	195232-002	1	CARD,RTF
8	196823-002	1	CARD,RTFCOA
9	213349-001	1	POWERCORD
10	307366-001	1	MODEMCABLE

FIG. 4(B)

5

Lacking assembly report			
Client code	Assembly code	Quantity	Date
1JOADSY80031	113823-121	1	2000/2/25
1JOADSY80031	155166-001	1	2000/2/25
1JOADSY80031	159224-001	1	2000/2/25
1JOADSX80002	113823-121	1	2000/2/25
1JOADSX80002	159224-001	1	2000/2/25
1JOADSX80002	178655-002	1	2000/2/25
1JOADSX80002	180680-121	1	2000/2/25
1JOADSX80002	182761-051	1	2000/2/25
1JOADSX80002	191841-002	1	2000/2/25
1JOADSX80002	195232-002	1	2000/2/25
1JOADSX80002	196823-002	1	2000/2/25
1JOADSX80002	213349-001	1	2000/2/25
1JOADSX80002	307366-001	1	2000/2/25
1JOAFL63600V	112666-008	1	2000/2/25
1JOAFL63600V	128676-002	1	2000/2/25